



### TO BE PERFORMED BY QUALIFIED PERSONNEL

#### CARE and CLEANING

1. Touch and hold the **BUNN** logo for a few seconds until the **SERVICE ACCESS** screen appears.
2. From the **SERVICE ACCESS** screen, press the **CARE AND CLEANING** button.
3. Select one of the three cleaning tabs: **Clean**, **Rinse**, or **Swiper**.




Follow the picture prompts to complete the action.



#### ACTIVE NOTICES

1. If the “i” button at the bottom of the screen appears; press it to view the message.
2. Press the **ACTIVE NOTICES** icon from the **SERVICE ACCESS** screen to view all the current notices.
3. The **ACTIVE NOTICES** screen will display suggested actions for alerts

**NOTE: Service Contact** information is also provided on this screen.



#### SERVICE CALLS:

For issues regarding service please call 800-420-2866. Please be ready to provide the service agent with the serial number of the machine.

**Bunn-O-Matic Corporation**

5020 Ash Grove Drive, Springfield, Illinois 62711 | Phone (217) 529-6601 | Fax (217) 529-6644